

273 Projects of XII Plan

Statewise Status of Village Inspection under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		Scope	No. of Villages Inspected	Scope	No. of Villages Inspected	Scope	No. of Villages Inspected
1	Assam	5635	2414	2254	308	113	0
2	Bihar	12836	5718	5134	1648	247	160
3	Chhattisgarh	1618	1932	650	650	32	32
4	J&K	104	0	41	0	3	0
5	Jharkhand	9046	1076	3618	311	181	31
6	Karnataka	4603	3508	1841	1024	91	36
7	MP	13091	15826	4484	3716	262	177
8	Manipur	898	93	359	16	19	0
9	Mizoram	19	19	19	10	0	0
10	Nagaland	417	47	55	10	11	0
11	Orissa	22083	6669	6968	1443	439	84
12	Rajasthan	12699	9246	5079	4342	253	190
13	Tripura	384	258	154	110	8	2
14	Uttar Pradesh	34589	25139	12562	7124	672	306
15	West Bengal	2816	3179	1126	1038	56	56
Total		120838	75124	44069	21750	2387	1074

273 Projects of XII Plan

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Assam	24849	7116	2624	131	0	0
2	Bihar	105172	39678	45845	19123	4781	1171
3	Chhattisgarh	16968	16968	6460	6460	1117	609
4	J&K	0	0	0	0	0	0
5	Jharkhand	21838	8479	3277	103	1878	69
6	Karnataka	18161	17798	7699	7699	575	109
7	MP	84103	82313	86329	71905	27754	18137
8	Manipur	1355	714	1291	619	0	0
9	Mizoram	232	232	57	53	0	0
10	Nagaland	203	203	149	126	0	0
11	Orissa	57033	43490	22867	7700	6622	2965
12	Rajasthan	31775	29819	129847	89362	33807	24240
13	Tripura	2515	2515	1779	1779	87	87
14	Uttar Pradesh	339922	213969	141097	53933	27588	16655
15	West Bengal	19928	19928	11755	10821	1434	1434
Total		724054	483222	460716	269814	105643	65476

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.

72 Projects of XI Plan Phase-II

Statewise Status of Village Inspected under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		Scope of TPIA	No. of Villages Inspected	Scope of RQM	No. of Villages Inspected	Scope of NQM	No. of Villages Inspected
1	Bihar	7083	3414	2833	1809	143	143
2	Chhattisgarh	602	1076	241	241	12	8
3	Haryana**	313	339	125	0	6	0
4	Karnataka	298	320	117	117	6	6
5	Kerala	247	268	128	128	7	7
6	MP	7908	7500	3157	2184	160	108
7	Maharashtra	415	684	166	166	11	11
8	Tamil Nadu	365	248	146	95	8	8
9	Uttar Pradesh	9949	11381	4008	3502	199	167
10	West Bengal	153	73	61	20	3	1
Total		27331	25303	10934	8262	555	459

** RQM villages inspections are in progress

72 Projects of XI Plan Phase-II

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Bihar	55998	10841	15835	3997	13128	5883
2	Chhattisgarh	3320	3320	11050	11050	783	659
3	Haryana**	1004	289	0	0	0	0
4	Karnataka	1890	1890	1918	1918	98	98
5	Kerala	639	639	2542	2542	131	131
6	MP	64554	62068	144213	97992	7752	5014
7	Maharashtra	1662	1662	9845	9845	219	219
8	Tamil Nadu	1509	1509	1063	1063	156	0
9	Uttar Pradesh	151845	99463	147288	93071	14739	11049
10	West Bengal	501	501	573	573	170	170
Total		282922	182182	334327	222051	37176	23223

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.

** Inspection by RQM is isn progress

341 Projects of XI Plan Phase-I

Statewise Status of Village Inspected under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		Scope of TPIA	No. of Villages Inspected	Scope of RQM	No. of Villages Inspected	Scope of NQM	No. of Villages Inspected
1	Andhra Pradesh	2638	2969	586	586	58	58
2	Arunachal Pradesh	1493	1697	335	335	30	30
3	Assam	9282	5693	1923	1923	184	184
4	Bihar	5513	5003	1053	1053	119	119
5	Chhattisgarh	6741	4645	1355	1172	138	138
6	Gujarat	7027	6781	1560	1560	155	155
7	Haryana	2081	2030	461	461	43	43
8	Himachal Pradesh	3763	3853	965	965	87	87
9	J&K	1110	798	254	254	25	25
10	Jharkhand	6313	3863	1419	1299	130	130
11	Karnataka	2855	2688	713	713	58	58
12	Kerala	279	299	59	59	6	6
13	MP	11937	11485	2231	2175	229	219
14	Maharashtra	15516	17964	3637	3637	357	357
15	Manipur	902	793	180	152	19	19
16	Meghalaya	2072	598	422	422	42	42
17	Mizoram	200	205	41	41	6	6
18	Nagaland	482	479	100	100	10	10
19	Orissa	17743	14597	3782	3782	381	381
20	Punjab	3149	3096	645	645	65	65
21	Rajasthan	10566	9129	2201	2201	220	220
22	Sikkim	132	135	27	27	3	3
23	Tamil Nadu	4837	6955	1242	1242	102	102
24	Tripura	340	345	69	69	8	8
25	West Bengal	11950	9979	2490	2490	235	235
Total		128909	116079	27750	27363	2710	2700

1. TPIA Reports from some of the states are awaited

341 Projects of XI Plan Phase-I

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.10.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Andhra Pradesh	6624	6624	1951	1951	668	668
2	Arunachal Pradesh	2615	2615	3383	3383	618	618
3	Assam	17916	17916	11912	11912	188	188
4	Bihar	40710	21828	13676	12140	1400	1151
5	Chhattisgarh	5084	5080	3913	3913	1494	1494
6	Gujarat	36686	36686	2641	2641	1667	1667
7	Haryana	18257	18257	2159	2159	447	447
8	Himachal Pradesh	1860	1860	2480	2480	2253	2253
9	J&K	11507	10866	5158	5158	318	266
10	Jharkhand	16476	16092	12549	12549	1162	1162
11	Karnataka	5204	5204	4600	4600	768	768
12	Kerala	264	264	281	281	210	210
13	MP	41306	38589	12791	12791	3451	3208
14	Maharashtra	31011	31011	4949	4949	3183	3183
15	Manipur	13576	5312	15211	700	653	338
16	Meghalaya	1730	1730	1154	1154	554	554
17	Mizoram	1079	1079	193	193	113	113
18	Nagaland	1810	1810	540	540	188	188
19	Orissa	32972	29906	2814	2814	4159	4159
20	Punjab	12406	9756	2269	2269	1051	1051
21	Rajasthan	94635	93437	28112	28112	1882	1882
22	Sikkim	6	6	274	274	50	50
23	Tamil Nadu	15145	15145	6021	6021	1142	1142
24	Tripura	643	643	266	266	142	142
25	West Bengal	49539	49539	28461	28461	2213	2213
Total		459061	421255	167758	151711	29974	29115

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.